




## 2-Step Toe Component Identification Process Atomic “Evox 2.8” / Atomic “FFG 8”

### **BEFORE REMOVING THE TOE COMPONENT FROM THE SKI:**


**Step 1:** Check the Atomic binding for the “Evox 2.8” or “FFG 8” brand. Referring to the pictures and markings indicated on the pages below, answer the following question:

Is the binding an  **ATOMIC** branded model **Evox 2.8**, **Evox 2.8+**, **Evox 2.8++**, or **FFG 8**?

**YES** – Then, please proceed to **Step 2**.

**NO** – The toe component of this Atomic-brand binding is **NOT** subject to this recall.

### **Atomic Evox 2.8**



# Atomic FFG 8



[Step 2 is on the next page]



**Step 2:** (If answered "YES" to **Step 1**) Inspect the toe component for a production date code found on the center plate where the toe of the ski boot contacts the toe component, as indicated in the following picture.



**PRODUCTION DATE CODE LOCATION**

Does the production date code end in the number "8" (for 2008)?

**YES** – The toe component of this binding **IS** subject to recall.

**NO** – This binding is **NOT** subject to the recall.

If the toe component of the binding **IS** subject to the recall, then:

- **Consumers** should NOT DISASSEMBLE the bindings. Consumers should bring the Atomic bindings to an authorized Atomic USA Ski Dealer, and the authorized dealer will follow the recall procedures and replace the toe component of the binding. A list of authorized dealers can be found on the [www.atomicsnow.com](http://www.atomicsnow.com) website.
- **Authorized Dealers** should follow items 3-8 at the end of the Dealer Guidelines, which have been sent to authorized dealers.